



Features

- ◆ High-strength load cell
- ◆ Aluminum die-casting case
- ◆ LED display, digital height 30mm
- ◆ American standard bow shackle
- ◆ American standard eye hook
- ◆ High capacity rechargeable battery
- ◆ Remote control

Functions

Zero	Digital Calibration
Tare	3-point Linearity Correction
Hold	lb/kg Switch
Battery Supervision	Division Switch
Overload Alarm/ Record	Gravity Acceleration Set

Specification

Accuracy class	OIML III
Tare range	100%F.S.
Settling Time	5-8s
Safe Overload	125%F.S.
Limited Load	400%F.S.
Overload alarm	100%F.S.
Battery	6V/4AH
Work Temperature	-10°C~40°C
Battery life	>80h

MOLTON IRON TEMP.	1000°C	1200°C	1400°C	1500°C
SAFE DISTANCE	2500MM	3000MM	4000MM	5000MM

Included Accessory



Battery



Remote control



Adaptor

Model	Max. Capacity (kg)	Division (kg)	Accuracy	Size (mm)								Net Weight (kg)
				A	B	C	D	E	F	G	H	
OCS-0.5t	500	0.5	OIML III	141	91	100	33	85	30	26	24	1.8
OCS-1t	1000	1		205	134	150	39	98	50	33	28	4.4
OCS-2t	2000	1		210	170	205	530	76	63	46	40	13.5
OCS-3t	3000	1		210	170	205	530	76	63	46	40	13.5
OCS-5t	5000	2		210	170	205	620	88	78	60	52	18.5
OCS-10t	10000	5		210	170	205	660	114	92	71	55	30
OCS-15t	15000	5		210	170	205	740	128	97	80	68	36.5
OCS-20t	20000	10		305	200	310	1005	160	245	130	280	115
OCS-30t	30000	10		420	317	400	1450	230	255	160	310	135

